

Summary of Facility Information in the County of Deer Lodge

Owner Name and Address: Sutey Oil Co Inc 2000 Holmes Ave Butte MT 59701 Phone: (406) 494-2305

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1200101	Thriftway Super Stop 7	2035 W Park Ave	Anaconda	59711	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
2 / 05 Currently in Use	2047	7/1/1993 13 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
3 / 04 Currently in Use	2046	7/1/1993 13 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
4 / 02 Currently in Use	2045	12/31/1971 34 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Deer Lodge

Owner Name and Address: Teds Gas & Repair Service Inc 701 E Park Ave Anaconda MT 59711 Phone: (406) 563-7351

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1201470	Teds Gas & Repair Service Inc	701 E Park Ave	Anaconda	59711	(406) 563-7351

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 10 Currently in Use	2096	5/1/1994 12 / No	Diesel 5,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
7 / 08 Currently in Use	2094	5/1/1994 12 / No	Gasoline 5,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
8 / 09 Currently in Use	2095	5/1/1994 12 / No	Gasoline 6,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Deer Lodge

Owner Name and Address: Sutey Oil Co Inc 2000 Holmes Ave Butte MT 59701 Phone: (406) 494-2305

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1207938	Thriftway Super Stop 3	1420 E Park Ave	Anaconda	59711	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 08 Currently in Use	2050	9/1/1990 15 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 07 Currently in Use	2049	9/1/1990 15 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 06 Currently in Use	2048	9/1/1990 15 / No	Gasoline 15,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
9 / 10 Currently in Use	2052	9/1/1990 15 / No	Diesel 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
10 / 09 Currently in Use	2051	9/1/1990 15 / No	Diesel 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Deer Lodge

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1208668	Town Pump Inc Anaconda 2	819 W Park Ave	Anaconda	59711	

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
1 / 06 Currently in Use	2410	4/1/1991 15 / No	Diesel 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	<input checked="" type="radio"/>	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		No Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	<input checked="" type="radio"/>	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
2 / 05 Currently in Use	2409	4/1/1991 15 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	<input checked="" type="radio"/>	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		No Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	<input checked="" type="radio"/>	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
5 / 03 Currently in Use	2407	4/1/1991 15 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	<input checked="" type="radio"/>	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		No Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	<input checked="" type="radio"/>	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
6 / 04 Currently in Use	2408	4/1/1991 15 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	<input checked="" type="radio"/>	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		No Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	<input checked="" type="radio"/>	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Deer Lodge

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1209326	Town Pump Inc Anaconda 1	Old Highway 10A E	Anaconda	59711	(406) 563-0000

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 08 Currently in Use	2414	11/1/1994 11 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div>(A) (B) (C) (D) (E) (F) (G) (H) (I) (J) (K) (L)</div> <div>(B) (D) (E) (F) (H) (I) (J) (K) (L)</div>	Yes Yes Yes Yes
2 / 07 Currently in Use	2413	12/1/1994 11 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div>(A) (B) (C) (D) (E) (F) (G) (H) (I) (J) (K) (L)</div> <div>(B) (D) (E) (F) (H) (I) (J) (K) (L)</div>	Yes Yes Yes Yes
3 / 06 Currently in Use	2412	5/1/1991 15 / No	Gasoline 12,000	Epoxy Coated Steel Impressed Current	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div>(A) (B) (C) (D) (E) (F) (G) (H) (I) (J) (K) (L)</div> <div>(B) (D) (E) (F) (G) (H) (J) (K) (L)</div>	Yes Yes Yes Yes
4 / 05 Currently in Use	2411	5/1/1991 15 / No	Diesel 12,000	Epoxy Coated Steel Impressed Current	Flexible Plastic Double-Walled	Pressurized	<div>(A) (B) (C) (D) (E) (F) (G) (H) (I) (J) (K) (L)</div> <div>(B) (D) (E) (F) (H) (I) (J) (K) (L)</div>	Yes Yes Yes Yes
9 / 09 Currently In Use	4574	7/1/2001 05 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div>(A) (B) (C) (D) (E) (F) (H) (I) (J) (K) (L)</div> <div>(B) (D) (E) (F) (H) (I) (J) (K) (L)</div>	Yes Yes Yes Yes
10 / 10 Currently In Use	4575	7/1/2001 05 / No	Diesel 5,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div>(A) (B) (C) (D) (E) (F) (H) (I) (J) (K) (L)</div> <div>(D) (D) (E) (F) (H) (I) (J) (K) (L)</div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Deer Lodge

Owner Name and Address: RDM Multi Enterprises Inc 105 N Silver St Anaconda MT 59711 Phone: (406) 563-3433

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1210912	RDM Multi Enterprises Inc		Anaconda	59711	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / S1 Currently in Use	1836	4/16/1985 21 / Ye	Used Oil 12,800	Unknown None	Bare Steel Double-Walled/Non-Corro	Pressurized	<div style="display: flex; justify-content: space-between; font-size: 0.8em;"> (A) (B) (C) (D) (E) (F) (G) (H) (I) (J) (K) (L) </div> <div style="display: flex; justify-content: space-between; font-size: 0.8em;"> (B) (D) (E) (F) (G) (H) (I) (J) (K) (L) </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Deer Lodge

Owner Name and Address: Espeland Resort Properties LLC 1700 Fairmont Road Anaconda MT 59711 Phone: (406) 797-3501

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613976	Espeland Resort Properties LLC	1700 Fairmont Road	Anaconda	59711	(406) 797-3505

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C																								
2 / 02 Currently In Use	4187	4/1/2000 06 / No	Gasoline 3,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>●</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	●	H	I	J	K	L	B		D	E	F	G	H	I	●	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	●	H	I	J	K	L																					
B		D	E	F	G	H	I	●	K	L																						
3 / 03 Currently In Use	4188	4/1/2000 06 / No	Diesel 3,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>●</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	●	H	I	J	K	L	B		D	E	F	G	H	I	●	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	●	H	I	J	K	L																					
B		D	E	F	G	H	I	●	K	L																						

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Deer Lodge

Owner Name and Address: Department of Corrections 1539 11th Ave PO Box 201301 Helena MT 59620 Phone: (406) 444-4931

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1207585	Xanthopoulos Bldg	2 C St	Warm Springs	59756	(406) 693-7110

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
4 / 04 Currently in Use	829	1/1/1987 19 / No	Diesel 2,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	U.S. Suction	<div><div>A B C ● E F G H I J K L</div><div>B ● E F ● H I J K L</div></div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed